


# Manual 03, Revision 69

## Transmission Operations

Rob Dropkin, Sr. Engineer II  
Transmission Operations

Markets Implementation Committee  
October 9, 2025

- **Revision 69 (11/20/2025):**
  - Periodic Review
  - Section 2.1.1 – Clarify language in regard to the LD rating requirement



**SME/Presenter:**

Rob Dropkin,

[Robert.Dropkin@pjm.com](mailto:Robert.Dropkin@pjm.com)

**M-03 Change Contact:**

[M03\\_Change@pjm.com](mailto:M03_Change@pjm.com)

**Manual 03, Rev 69 – Periodic Review**

A green speech bubble containing a white question mark, positioned above a blue speech bubble with three horizontal lines, indicating a question or contact point.

?

**Member Hotline**

(610) 666 – 8980

(866) 400 – 8980

[custsvc@pjm.com](mailto:custsvc@pjm.com)

# Appendix

- **Revision 67.1 (06/05/2025):**

- RTO Section 1.1.6: Section moved to Manual 03, Section 1.9 Recognition of Automatic Sectionalizing Schemes.
- RTO Section 1.1.7: Section moved to Manual 03, Section 1.8 Automatic Remedial Action Scheme (RAS) Operating Criteria.
- RTO Section 1.1.8: Updated Calvert Cliffs ownership.
- RTO Section 1.1.8: Revised Surry NPIR voltage limits.
- RTO Section 1.1.8: Updated Byron NPIR ownership.
- RTO Section 1.1.8: Revised Braidwood NPIR voltage limit and ownership.
- AEP Section 1.4.4: Updated Gavin – Rolling Hills Stability table.
- BGE Section 1.5.1: Added clarification note for Calvert Cliffs stability procedure.
- PECO Section 1.16.4: Corrected rating on Limerick 4A and 4B table.
- PSEG Section 1.19.1: Reformatted the Artificial Island stability table.