

# Executive Summary Manual Changes

<b>Effective Date</b>	January 2026 (upon MRC endorsement)
<b>Impacted Manual #(s)/Manual Title(s):</b> Regional Transmission and Energy Scheduling Practices	
<b>Conforming Order(s):</b> Docket No. RM05-5-31; Order No. 676-K	
<b>Associated Issue Tracking Title:</b>	N/A
<b>Committee Approval Path - What committee(s) have already seen these changes?</b> Operating Committee	
<b>MRC 1<sup>st</sup> read date:</b>	12/17/2025
<b>MRC voting date:</b>	01/22/2026
<b>Impacted Manual sections:</b> Sections 1.1.1, 1.1.4, 1.2, 1.2.3, 1.6, 1.9, 1.21.1, 2.2.4, 2.6, and 2.7	
<b>Reason for change:</b> Conforming changes to NAESB 4.0 Business Practice Standards  Administrative clean up	
<b>Summary of the changes:</b> <ul style="list-style-type: none"> <li>Section 1 <ul style="list-style-type: none"> <li>Section 1.1.1 – Fixed broken links</li> <li>Section 1.1.4 - Fixed broken link to PJM source/sink combinations</li> <li>Section 1.2 – Fixed broken link</li> <li>Section 1.2.3 - Minor addition for clarification</li> </ul> </li> </ul>	

- Section 1.6 - Updated customer confirmation timings in accordance with new NAESB 4.0 requirements. Updated reseller response to rebid timings for consistency.
- Section 1.9 – Minor update for clarification
- Section 1.21.1 – Fixed broken links
- Section 2
  - Section 2.2.4 - Minor update to clarify timing of ramp limit validations
  - Section 2.6 - Administrative update to consolidate and reformat this entire section for clarity and consistency with interchange curtailment/recall procedures in Manual 13: Emergency Operations. No changes to PJM business processes.
  - Section 2.7 – Removed redundant link. Product list is provided separately under section 1.1.3