



# Executive Summary Manual Changes

<b>Effective Date</b>	May 26, 2026
<b>Impacted Manual #(s)/Manual Title(s):</b> Manual 12: Balancing Operations	
<b>Conforming Order(s):</b> N/A	
<b>Associated Issue Tracking Title:</b>	N/A
<b>Committee Approval Path - What committee(s) have already seen these changes?</b> SOS	
<b>MRC 1<sup>st</sup> read date:</b>	3/25/26
<b>MRC voting date:</b>	4/22/26
<b>Impacted Manual sections:</b> 1.1, 2.1.2, 2.1.3, 3.1.1, 3.1.2, 3.2.1, 4.1.2, 4.2, 4.5.1, Attachment F	
<b>Reason for change:</b> Periodic Review	
<b>Summary of the changes:</b> <b>Revision 57 (05/26/2026):</b> <ul style="list-style-type: none"><li>• Periodic Review updated to address:<ul style="list-style-type: none"><li>◦ Updated manual ownership from Kevin Hatch to Paul Dajewski</li></ul></li></ul>	

- Cover-to-cover changes: Corrected punctuation, spelling and grammar, changed from exhibit numbers to exhibit titles in body, updated BAL-001, BAL-002, BAL-003, and BAL-005 for new revisions
- Removed references to retired NERC standards INT-001-3 and INT-004-3.1
- Removed "Dispatching Timeline" exhibit from Section 1.1
- Updated Section 2.1.2 to remove Hydro Calculator, changed PI Process Book to PI Vision, and added Transient Stability Analysis
- Updated Section 2.1.3 Phone Recording Device description
- Updated Section 3.1.1 PJM Area Control Error
- Updated Real Time Data Sources in Section 3.1.2
- Updated to ensure time error correction All-Call is initiated in advance of the time error correction in Section 3.2.1
- Updated PJM Actions for loading synchronized reserves in Section 4.1.2
- Renamed Section 4.2 from Shared Reserves to Simultaneous Activation of Reserves (NPCC)
- Changed shared reserves to activated reserves in Section 4.2
- Removed specific control zones in Section 4.2
- Updated Section 4.5.1 to include the specific Black Start Service Section of this manual