

Manual 36: System Restoration Revision 29 Updates

Rich Brown Manager, System Operator Training Markets & Reliability Committee May 26, 2021



Summary of M36 Changes

- Attachment B: Exhibit 16 replaced with a clearer image
- Attachment F: Deleted; restoration plans in eDART
- Attachment G: Table 1: Updated TO list and due dates
- Attachment H:
 - Updated Under Frequency Load Shed table with new data
 - Added note that PJM's UFLS program does not require automatic switching of Capacitor banks, Transmission Lines, or reactors

Manual 36: System Restoration, Revision 29




Changes Subsequent to April MRC First Read

- Attachment B: Exhibit 16 replaced with a clearer image
- Attachment H:
 - Updated Under Frequency Load Shed table with new data
 - Added note: PRC-006 R10

PJM's UFLS program does not require automatic switching of capacitor banks, transmission lines, or reactors. However, if a Transmission Owner uses automatic switching in order to control over-voltage as a result of underfrequency load shedding, the Transmission Owner shall inform PJM (NERC.Transmission.Planner@pjm.com), in accordance with PRC-006 R10.

Manual 36: System Restoration, Revision 29







SME/Presenter: Rich Brown richard.brown@pjm.com

Manual 36, Rev 29 – Periodic Review

Member Hotline (610) 666 – 8980 (866) 400 – 8980 custsvc@pjm.com