



# Manual-36 System Restoration Update

Liem Hoang  
System Operating Subcommittee  
May 2, 2019

- Annual Update Cover to cover review.
  - Terminology, grammatical changes, and clarifications throughout.
- Updated NERC standard references from EOP-005-2 and EOP-006-2 to EOP-005-3 and EOP-006-3.
- References Section: Removed TO/EOP-005 mapping link and replaced with TO/TOP Matrix site.
- 3.1.7 and 7.2: Added section description and purpose statements.

- Attachment F:
  - Changed title from Transmission Owner and Black Start Supporting Documentation References to Transmission Owner Special Procedures.
  - Removed language in reference to training record, black start database, and Transmission Owner plan reference to EOP-005-2.
- Attachment G:
  - Added coordination review with neighbors in case of conflicts with a particular restoration plan.
  - Modified distribution list for M-36.
- Attachment H: Updated attachment with new UFLS data.
- Attachment I: Deleted attachment which had specified M-36 Sections corresponding to EOP-005 and EOP-006 Requirements.

- First Reads
  - SOS 4/4/19
  - OC 4/9/19
  - MRC 4/25/19
- Second Reads / Endorsements
  - SOS 5/2/19
  - OC 5/14/19
  - MRC 5/30/19
- Effective
  - 6/20/19