

SCHEDULE 6 OF THE PJM OPERATING AGREEMENT

Section 1.5.8(n) Reliability Violations on Transmission Facilities Below 200 kV

Pursuant to the expansion planning process set forth in Sections 1.5.1 through 1.5.6 of Schedule 6, the Office of the Interconnection shall identify reliability violations on facilities below 200 kV. The Office of the Interconnection shall not post such a violation pursuant to Section 1.5.8(b) of this Schedule 6 for inclusion in a proposal window pursuant to Section 1.5.8(c) unless the identified violation(s) satisfies one of the following exceptions: (i) the reliability violations are thermal overload violations identified on multiple transmission lines and/or transformers rated below 200 kV that are impacted by a common contingent element, such that multiple reliability violations could be addressed by one or more solutions, including but not limited to a higher voltage solution; or (ii) the reliability violations are thermal overload violations identified on multiple transmission lines and/or transformers rated below 200 kV and the Office of the Interconnection determines that given the location and electrical features of the violations one or more solutions could potentially address or reduce the flow on multiple lower voltage facilities, thereby eliminating the multiple reliability violations. If the reliability violation is identified on multiple facilities rated below 200 kV that are determined by the Office of the Interconnection to meet one of the two exceptions stated above, the Office of the Interconnection shall post on the PJM website the reliability violations to be included in a proposal window consistent with Section 1.5.8(c) of Schedule 6. If the Office of the Interconnection determines that the identified reliability violations do not satisfy either of the two exceptions stated above, the Office of the Interconnection shall post on the PJM website for review and comment by the Transmission Expansion Advisory Committee and other stakeholders descriptions of the below 200 kV reliability violations that will not be included in a proposal window pursuant to Section 1.5.8(c). The descriptions shall include an explanation of the decision to not include the below 200 kV reliability violation(s) in a Section 1.5.8(c) proposal window, a description of the facility on which the violation(s) is found, the Zone in which the facility is located, and notice that such construction responsibility for and ownership of the project that resolves such below 200 kV reliability violation will be designated to the incumbent Transmission Owner. After the descriptions are posted on the PJM website, stakeholders shall have reasonable opportunity to provide comments ~~to the Office of the Interconnection for~~ consideration by the Office of the Interconnection. With the exception of Immediate-need Reliability Projects under section 1.5.8(m) of this Schedule 6, PJM will not select an above 200 kV solution for inclusion in the recommended plan that would address a reliability violation on a below 200 kV transmission facility without posting the violation for inclusion in a proposal window consistent with Section 1.5.8(c) of Schedule 6. All written comments received by the Office of the Interconnection shall be publicly available on the PJM website.