

Summary of M-03A Rev. 15 Changes

Diane Lake
Operating Committee
July 10, 2018

M-03A, Rev. 15 Changes

Overview of Changes:

- Administrative Updates Cover to Cover Review, Exhibit number references updated, formatting, etc.
- Section 1.6:
 - Sentence added to note applicability of technical requirements to PJM TOP facilities and facilities outside the PJM TOP area.
 - Section 1.6: Reference to Manual 1, Section 3.8.1 added for specifics on coordination efforts and allowable timeframes for ICCP planned outages.

Section 2.2:

- New section added for Flow Circuit Breakers outlining description and change instructions.
- Note modified to reference Manual 1, Control Center and Data Exchange Requirements.

Section 2.4:

- Updated steps added to access Transmission Facilities page on pjm.com.
- Exhibit 2: Updated screenshot from new location of Transmission Facilities pages on pjm.com.
- Section 2.4.3 updated to reflect current process steps.



M03A, Rev. 15 Changes

Overview of Changes: (continued)

- Section 3.2: New section for Phased Projects added, with accompanying Note providing an example.
- Section 5: Reference to Contingency Analysis (CA) changed to Real-Time Contingency
 Analysis (RTCA) to identify function by NERC naming convention and Security Analysis (SA) to
 represent PJM tool used to run contingency analysis
- Appendix C: Outlined outage reporting requirements on a per priority basis and referenced
 Manual 03 for latest details