

**WITHDRAWN DEACTIVATIONS
(as of April 20, 2011)**

Unit	Capacity	Trans Zone	Age (Years)	Official Owner Request	Requested Deactivation Date	Actual Deactivation Date	PJM Reliability Status ¹	Comments
Shawnee CT	20	ME	31	2/12/2004	Black Start Unit operational until at least 12/05	Deferred	Reliability Issue - Blackstart	Rolling two-year commitment to provide black start service.
Blossburg CT	19	PN	32	2/12/2004	Black Start Unit operational until at least 12/05	Deferred	Reliability Issue - Blackstart	Rolling two-year commitment to provide black start service.
Glen Gardner 1&5	40	JC	32	2/12/2004	Black Start Unit operational until at least 12/05	Deferred	Reliability Issue - Blackstart	Rolling two-year commitment to provide black start service.
Gilbert 1&4 CTs	50	JC	33	2/12/2004	Black Start Unit operational until at least 12/05	Deferred	Reliability Issue - Blackstart	Rolling two-year commitment to provide black start service.
Gilbert 2 & 3 CTs	48	JC	33	2/12/2004	Request Withdrawn	Withdrawn	No Reliability Issues	Deactivation notice withdrawn 4/26/2004.
Glen Gardner 2-4, 6-8 CTs	120	JC	32	2/12/2004	Request Withdrawn	Withdrawn	No Reliability Issues	Deactivation notice withdrawn 4/26/2004.
Werner 1-4 CTs	212	JC	32	2/12/2004	Request Withdrawn	Withdrawn	No Reliability Issues	Deactivation notice withdrawn 4/26/2004.
Hudson 2	608	PS	38	10/2/2006	12/31/2006	Withdrawn	Reliability Issues Identified	Deactivation notice withdrawn 12/4/2006.
B L England 1	129	AE	41	9/21/2004	12/15/2007	Withdrawn	Reliability Issues Identified and expected to be resolved by 12/2007	Deactivation notice withdrawn 2/19/2007.
B L England 2	155	AE	39	9/21/2004	12/15/2007	Withdrawn	Reliability Issues Identified and expected to be resolved by 12/2007	Deactivation notice withdrawn 2/19/2007.
B L England 3	155	AE	29	9/21/2004	12/15/2007	Withdrawn	Reliability Issues Identified and expected to be resolved by 12/2007	Deactivation notice withdrawn 2/19/2007.
B L England IC1-IC4	8	AE	42	9/21/2004	12/15/2007	Withdrawn	Reliability Issues Identified and expected to be resolved by 12/2007	Deactivation notice withdrawn 2/19/2007.
STI GT1 & ST1 (Cat Tractor)	13	ME	17	9/19/2006	11/1/2006	Withdrawn	No Reliability Issues	Deactivation notice withdrawn 4/2/2007.
Brunot Island 4CC	244	DUQ	31	12/2/2005	1/1/2006	Withdrawn	Reliability Issues Identified and resolved, RMR payments terminated effective 7/5/2007.	Deactivation notice withdrawn 5/16/2007.
Prime Energy (Marcal)	47	PS	16	9/16/2005	10/31/2005	Deactivated 1/9/2006, Reactivated for 6/1/2007	No Reliability Issues	Queue R66 (1/12/2007). Offered and cleared in RPM auction for 2007/2008.
Parlin	114	JC	15	2/28/2006	5/31/2006	Deactivated 4/10/2006, Reactivated for 6/1/2008	No Reliability Issues	Queue S25 (4/9/2007). Offered and cleared in RPM auction for 2008/2009.
Howard M. Down (Vineland) Unit 9	17	AE	45	2/24/2006	5/31/2006	Deactivated 6/1/2006, Reactivated for 6/1/2008	No Reliability Issues	Queue S43 (5/15/2007). Offered and cleared in RPM auction for 2008/2009.
Gould Street	101	BGE	51	11/4/2003	11/1/2003	Deactivated 12/1/2003, Reactivated for 6/1/2008	No Reliability Issues	Queue S67 (7/26/2007).
Sewaren 1	104	PS	55	9/8/2004	12/7/2004	Withdrawn	Reliability Issues Identified - Unit retained through summer 2008	Sewaren Units 1-4 were offered and cleared in RPM for a delivery year beyond the timeframe for which they were required for reliability. A new deactivation request will be needed if the units are to be retired.
Sewaren 2	118	PS	55	9/8/2004	12/7/2004	Withdrawn	Reliability Issues Identified - Unit retained through summer 2008	Sewaren Units 1-4 were offered and cleared in RPM for a delivery year beyond the timeframe for which they were required for reliability. A new deactivation request will be needed if the units are to be retired.
Sewaren 3	107	PS	54	9/8/2004	12/7/2004	Withdrawn	Reliability Issues Identified - Unit retained through summer 2008	Sewaren Units 1-4 were offered and cleared in RPM for a delivery year beyond the timeframe for which they were required for reliability. A new deactivation request will be needed if the units are to be retired.
Sewaren 4	124	PS	52	9/8/2004	12/7/2004	Withdrawn	Reliability Issues Identified - Unit retained through summer 2008	Sewaren Units 1-4 were offered and cleared in RPM for a delivery year beyond the timeframe for which they were required for reliability. A new deactivation request will be needed if the units are to be retired.
Bergen 2	550	PS	5	1/15/2008	6/1/2011	Withdrawn	Reliability issues identified	Deactivation notice withdrawn 5/6/2008.
Warren 3 CT	57	PN	31	2/12/2004	10/1/2004	Deactivated 10/04/2004, Reactivated 04/11/2011	No Reliability Issues	Deactivated 10/04/2004, Reactivated 04/11/2011, (S103)

Total Withdrawn: 3160

Note (1): PJM Reliability Status column also contains links to additional information for requests with reliability issues posted to the PJM website.