



Executive Summary Manual Changes

Effective Date	January 2026 (upon MRC endorsement)
Impacted Manual #(s)/Manual Title(s): Regional Transmission and Energy Scheduling Practices	
Conforming Order(s): Docket No. RM05-5-31; Order No. 676-K	
Associated Issue Tracking Title:	N/A
Committee Approval Path - What committee(s) have already seen these changes? Operating Committee, Markets and Reliability Committee	
MRC 1st read date:	12/17/2025
MRC voting date:	01/22/2026
Impacted Manual sections: Sections 1.1.1, 1.1.4, 1.2, 1.2.3, 1.6, 1.9, 1.21.1, 2.2.4, 2.6, and 2.7	
Reason for change: Conforming changes to NAESB 4.0 Business Practice Standards Administrative clean up	
Summary of the changes: <ul style="list-style-type: none">• Section 1<ul style="list-style-type: none">○ Section 1.1.1 – Fixed broken links○ Section 1.1.4 - Fixed broken link to PJM source/sink combinations○ Section 1.2 – Fixed broken link○ Section 1.2.3 - Minor addition for clarification	



Executive Summary Manual Changes

- Section 1.6 - Updated customer confirmation timings in accordance with new NAESB 4.0 requirements. Updated reseller response to rebid timings for consistency.
- Section 1.9 – Minor update for clarification
- Section 1.21.1 – Fixed broken links
- Section 2
 - Section 2.2.4 - Minor update to clarify timing of ramp limit validations
 - Section 2.6 - Administrative update to consolidate and reformat this entire section for clarity and consistency with interchange curtailment/recall procedures in Manual 13: Emergency Operations. No changes to PJM business processes.
 - Section 2.7 – Removed redundant link. Product list is provided separately under section 1.1.3