


Manual 03, Revision 69

Transmission Operations

Rob Dropkin, Sr. Engineer II
Transmission Operations

Systems Operations
Subcommittee
October 30, 2025

- **Revision 69 (11/20/2025):**
 - Periodic Review
 - Section 2.1.1 – Clarify language in regard to the LD rating requirement



SME/Presenter:

Rob Dropkin,

Robert.Dropkin@pjm.com

M-03 Change Contact:

M03_Change@pjm.com

Manual 03, Rev 69 – Periodic Review



Member Hotline

(610) 666 – 8980

(866) 400 – 8980

custsvc@pjm.com

Appendix


- **Revision 67.1 (06/05/2025):**

- RTO Section 1.1.6: Section moved to Manual 03, Section 1.9 Recognition of Automatic Sectionalizing Schemes.
- RTO Section 1.1.7: Section moved to Manual 03, Section 1.8 Automatic Remedial Action Scheme (RAS) Operating Criteria.
- RTO Section 1.1.8: Updated Calvert Cliffs ownership.
- RTO Section 1.1.8: Revised Surry NPIR voltage limits.
- RTO Section 1.1.8: Updated Byron NPIR ownership.
- RTO Section 1.1.8: Revised Braidwood NPIR voltage limit and ownership.
- AEP Section 1.4.4: Updated Gavin – Rolling Hills Stability table.
- BGE Section 1.5.1: Added clarification note for Calvert Cliffs stability procedure.
- PECO Section 1.16.4: Corrected rating on Limerick 4A and 4B table.
- PSEG Section 1.19.1: Reformatted the Artificial Island stability table.

**PROTECT THE
POWER GRID**
**THINK BEFORE
YOU CLICK!**



**BE ALERT TO
MALICIOUS PHISHING
EMAILS**



Report suspicious email activity to PJM.
Call (610) 666-2244 or email it_ops_ctr_shift@pjm.com