



Executive Summary Manual Changes

Effective Date	11/19/2024
Impacted Manual #(s)/Manual Title(s): Manual 15: Cost Development Guidelines	
Conforming Order(s):	
Associated Issue Tracking Title:	
Committee Approval Path - What committee(s) have already seen these changes? CDS, MIC/MRC, MC	
MRC 1st read date:	8/21/2024
MRC voting date:	9/25/2024
Impacted Manual sections: 2.6.11, 4.4, 5.4, 6.4, 7.2, 11.2.1, 13.3, Attachment B	
Reason for change: Biennial review changes	
Summary of the changes: Throughout – standardize spelling of No-load 2.6.11 - Remove table of original VOM Default values to avoid confusion 4.4, 5.4, 6.4 - Remove errant "+" from the end of the Startup Cost formula and change TRFC to TFRC 6.4 - Remove blank Note: box 7.2 - Remove 00, fix errant "(", fix summation notation 11.2.1 - Correct the fuel cost formula by changing the multiplication to division 13.3- Remove "Name to be determined" from Exhibit 26 Att. B - Update graphs to have appropriate Y-axis labels Update numbering of sections 3.3.1, 3.3.2, 4.3.1, 6.3.1, 6.3.2, 7.3.1	